

<i>Project Description</i>	<i>Results of the project</i>	<i>Year</i>	<i>Site</i>	<i>Client/Investor</i>
Environmental audit of the building complex				
Environmental assessment of past and current activities of trade and administrative centre	- compliance audit (phase I) - data evaluation & reporting	2005	Olomouc	URS Corporation
Environmental audit of part of the industrial area				
Environmental due diligence of previous industrial area of Aritma Vokovice	- compliance audit (phase I) - data evaluation & reporting	2005	Prague	ENVIROS
Environmental audit of three industrial sites				
Environmental due diligence of three sites where metal packaging products are generated	- compliance audit (phase I) - data evaluation & reporting	2005	Skrivany, Teplice, Znojmo	ERM
Environmental audit of two building complexes				
Environmental assessment of past and current activities of two trade and administrative centres	- asbestos presence - soil contamination - data evaluation & reporting	2005	Prague	ERM
Risk assessment of the ČD station in Lovosice				
environmental and human health risk assessment in Lovosice ČD station resulting from the large contamination with petroleum hydrocarbons in a consequence of spillage of fuels	- soil investigation - data evaluation & reporting	2004	ČD station Lovosice	ČD station Lovosice
Soil investigation of the former Slovnaft logistics sites in Pozdišovce and Ružomberok				
Site investigation of the former Slovnaft logistics sites in Slovakia	- soil investigation - data evaluation & reporting	2004	Slovnaft, a.s. in Pozdišovce and Ružomberok	Slovnaft, a.s.
Environmental audit of the food chain Penny Market Louny in complete with its outbuilding				
Due-diligence environmental audit of the food chain Penny Market Louny including its outbuilding	- compliance audit (phase I) data evaluation & reporting	2004	Penny Market in Louny	M.D.R., s.r.o.
Environmental audit in the premises of BS Most – Velebudická výsypka				
- due-diligence environmental audit of the premises of BS Most – Velebudická výsypka, shop floor including accessories and lands n° 271 and 276/41	- compliance audit (phase I) - data evaluation & reporting	2004	Premises BS Most – Velebudická výsypka in Zápy u Brandýsa nad Labem	Rödl&Partner, v.o.s.
Risk assessment of Beopetrol site in Bogutovac				

Environmental and human health risk assessment at Beopetrol site resulting from the large contamination with petroleum hydrocarbons in a consequence of spillage of fuels during NATO bombing	- soil & groundwater investigation (phase II) - risk assessment - data evaluation & reporting - phase I	2003	Beopetrol PJ Kraljevo in Bogutovac, Serbie and Monte Negro	Ministry of the Environment, Czech Republic
Soil & groundwater investigation of the site LACERTA, a.s. in Zápy u Brandýsa nad Labem				
Site investigation of the site contaminated by TPHs.	- soil & groundwater investigation (phase II) - data evaluation & reporting	2003	LACERTA, a.s. in Zápy u Brandýsa nad Labem	Administrator of the estate
Risk assessment of "CPP Transgas" site in Prague / Měcholupy - former gas plant (FGP)				
Assessment of risks for environment and public health resulting from the residual contamination of FGP site	- soil & groundwater investigation (phase II) - risk assessment - data evaluation & reporting - phase I	2002	FGP site in Prague / Měcholupy	ČPP Transgas s.p
Environmental audit of a refuelling & service boat in Prague				
Compliance environmental audit of a refuelling & service boat SP 150	- compliance audit (phase I) - data evaluation & reporting	2002	landing place "Na Františku" in Prague	Benzina Inc.
Environmental audit of the Czech army base in Aš - former military site				
Environmental audit of four former military sites before their acquisition by the Aš municipality	- soil & groundwater investigation (Phase II) - data evaluation & reporting	2002	former military sites in Aš	Town council Aš
Soil & groundwater investigation of the site Chemopetrol Litvínov - Třebusice				
Site investigation of the leading Czech petrochemical plant contaminated by TPHs	- soil & groundwater investigation (phase II) - data evaluation & reporting	2001	Premises of the Chemopetrol company in Litvínov-Třebusice	Chemopetrol Litvínov-Třebusice
Environmental audit of the "ČSPLO" refuelling site in Děčín - refuelling station				
Compliance environmental audit of ships refuelling station	- compliance audit (phase I) - data evaluation & reporting	2001	premises of refuelling station in Děčín	Benzina Inc
Environmental audit of the "ŽĎAS" sites - engineering and metallurgical plant				
Due-diligence environmental audit of a significant Czech engineering and metallurgical plant	- compliance audit (Phase I) - soil & groundwater investigation (Phase II) - data evaluation & reporting	2001	premises of the "ŽĎAS" plant in Žďár nad Sázavou, Přibyslav and Havlíčkův Brod	PCC Flow Technologies, USA
Environmental audit of the "Poldi" site in Kladno - metallurgical plant				

Due-diligence environmental audit of the former metallurgical plant; the site polluted by TPHs, PAHs, BTEX and CHCs	- soil & groundwater investigation (phase II) - environmental assessment - data evaluation & reporting - monitoring	2001	premises of the former metallurgical plant "Ocelárna	Wyman-Gordon USA
Environmental audit of a site near Nové Strašecí - recreational site				
Due-diligence environmental audit of a former recreational centre	- compliance audit (Phase I) - soil & groundwater investigation (Phase II) - data evaluation & reporting	2001	premises of the former recreational centre near Nové Strašecí	Městský úřad Nové Strašecí
Environmental audit of the "MSA" site in Dolní Benešov - engineering plant				
Due-diligence environmental audit of an engineering plant - the leading Czech producer of industrial valves	- compliance audit (Phase I) - soil & groundwater investigation (Phase II) - data evaluation & reporting	2001	premises of the "MSA" plant in Dolní Benešov	Wyman-Gordon USA
Soil & groundwater investigation of the Czech army base letiště Plzeň - Líně				
Site investigation of the Czech army base contaminated by TPHs	- soil & groundwater investigation (phase II) - data evaluation & reporting	2000	premises of the Czech army base in Plzeň-Líně	Czech army base letiště Plzeň-Líně
Soil & groundwater investigation at PetroHemija site in Pančevo, Yugoslavia - petrochemical plant				
Site investigation of the leading Yugoslavian petrochemical plant contaminated by CHCs, TPHs and Hg in consequence of NATO bombing	- soil & groundwater investigation (phase II) - data evaluation & reporting	2000	premises of the Petrohemija plant in Pančevo, Yugoslavia	HIP PetroHemija, d.o.o.
Soil investigation in the Železářny Hrádek – metal industry plant				
Site investigation of the metal industry plant contaminated by TPHs	- soil investigation - data evaluation and reporting	1999	Premises of the Železářny Hrádek plant	Železářny Hrádek
Soil & groundwater investigation at Lovochemie site in Lovosice - chemical plant				
Site investigation of the leading Czech fertilizer plant contaminated by TPHs and CHC	- soil & groundwater investigation (phase II) - data evaluation & reporting	1998	premises of the Lovochemie company in Lovosice	Lovochemie Inc. / Czech National Property Fund
Environmental audit of the OPTIMIT Odra site				
Due-diligence environmental audit of the chemical plant contaminated by TPHs and CHC	- compliance audit (phase I) - soil & groundwater investigation (Phase II) - data evaluation & reporting	1998	Premises of the OPTIMIT Odra in Odry	OPTIMIT Odry
Environmental audit in the AKUMA Mladá Boleslav company				
Due-diligence environmental audit of the chemical plant contaminated by TPHs and CHC	- compliance audit (phase I) - soil & groundwater investigation (Phase II) - data evaluation & reporting	1997	AKUMA Mladá Boleslav	AKUMA Mladá Boleslav company